

GREG BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

Representatives Present During the Inspection:					
OGM	Karl Houskeeper				

of

Inspection Report

Permit Number:	C0150015			
Inspection Type:	PARTIAL			
Inspection Date:	Saturday, October 23, 2010			
Start Date/Time:	10/23/2010 8:00:00 AM			
End Date/Time:	10/26/2010 1:00:00 PM			
Last Inspection:	Tuesday, September 14, 2010			

Inspector: Karl Houskeeper,

Weather: Partly Cloudy, Temp. 37 Deg. F.

InspectionID Report Number: 2538

Types of Operations

Accepted by: jhelfric 11/2/2010

Permitee: CONSOLIDATION COAL CO
Operator: CONSOLIDATION COAL CO

Site: **EMERY DEEP MINE**

Address: PO BOX 566, SESSER IL 62884

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

442.50	Total Permitted	
248.50	Total Disturbed	
	Phase I	
	Phase II	
	Phase III	

Mineral (Ownership
-----------	-----------

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Jaren Jorgensen, Consol, was present during the inspection.

Inspector's Signature:

Warl L. Lousberger

Date

Tuesday, October 26, 2010

Karl Houskeeper,

Inspector ID Number: 49

Permit Number: C0150015 Inspection Type: PARTIAL

Inspection Date: Saturday, October 23, 2010

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	✓		~	
3.	Topsoil	~		✓	
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.	a Roads: Construction, Maintenance, Surfacing				
16.	b Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other	✓		✓	

Permit Number: C0150015 Inspection Type: PARTIAL

Inspection Date: Saturday, October 23, 2010

Page 3 of 3

2. Signs and Markers

The mine identifications signs were observed in place at various points of access to the permit areas from public roads. The signs contained the required information.

3. Topsoil

Care needs to be taken to keep material off of the topsoil piles and topsoil berms.

22. Other

Upon observation of the wind fence it appears that the top section that was loose has now been secured. No new wind fence has been placed on the structure. From previous inspections it was noted that the intention was to purchase new wind fence and to replace tattered sections of the fence in an effort to remain in compliance with the commitments listed in the mining and reclamation plan (MRP). To present date this has not occurred. It is evident that efforts have been made to secure the existing wind fence. For the most part this has been successful. Once portions of the wind fence located on the lower course about in the middle or adjacent to the western water cannon can not be repaired, since this section is completely missing. The wind fence will continue to be monitored to assure that maintenance is done. Portions of the wind fence will eventually reach a point where maintenance by re-scureing the fence will no loger be possible and then the fence will need replacement.